

Oil Field Environmental Incident Summary

Incident: 20140113102813 **Date/Time of Notice:** 01/13/2014 10:18

Responsible Party: Oasis Petroleum

Well Operator: OASIS PETROLEUM NORTH AMERICA LLC

Well Name: WHITTEN 5393 11-3B

Field Name: SANISH

Well File #: 23476

Date Incident: 1/12/2014 **Time Incident:** 1200

Facility ID Number:

County: MOUNTRAIL

Twp: 153

Rng: 93

Sec: 3

Qtr: LO T4

Location Description:

Submitted By: Jared Iverson

Received By:

Contact Person: Jared Iverson
1001 FANNIN STE 1500
HOUSTON, TX 77002

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Miles

Distance Nearest Water Well: 1 Miles

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units
Oil	2	barrels	1	barrels
Brine	0	barrels	0	barrels
Other	0	barrels	0	barrels

Followup **Units**

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

We will conduct training for the truck drivers on the proper procedure for opening and closing production tanks.

Wastes Disposal Location: impacted material will be hauled to Clean Harbors.

Agencies Involved:

Updates

Date: 1/13/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from tank overflow remained on location, according to the report. NDIC retains oversight.